

**Photodocumentation – Vibratory Finishing Area – Building 3A
Baldwin Hardware Manufacturing Corporation
Reading, Pennsylvania**



Date	Viewpoint	View Direction	Description
June 6, 2008	Driveway East of Building 3A	East	Stain on Exterior Building Wall

**Photodocumentation – Vibratory Finishing Area – Building 3A
Baldwin Hardware Manufacturing Corporation
Reading, Pennsylvania**



Date	Viewpoint	View Direction	Description
June 6, 2008	Along Concrete Trench Within Building 3A	East	Concrete Trench – Note Pairs of Stakes Within Trench

**Photodocumentation – Vibratory Finishing Area – Building 3A
Baldwin Hardware Manufacturing Corporation
Reading, Pennsylvania**



Date	Viewpoint	View Direction	Description
June 6, 2008	At East End of Concrete Trench Within Building 3A	-	Concrete Trench – Note Pairs of Stakes Within Trench

**Photodocumentation – Vibratory Finishing Area – Building 3A
Baldwin Hardware Manufacturing Corporation
Reading, Pennsylvania**



Date	Viewpoint	View Direction	Description
June 6, 2008	Building 3A	North	Mid-Section of Concrete Trench Showing Location of the Sump

**Photodocumentation – Vibratory Finishing Area – Building 3A
Baldwin Hardware Manufacturing Corporation
Reading, Pennsylvania**



Date	Viewpoint	View Direction	Description
June 11, 2008	Building 3A	--	Core Through the East End of the Concrete Trench

**Photodocumentation – Vibratory Finishing Area – Building 3A
Baldwin Hardware Manufacturing Corporation
Reading, Pennsylvania**



Date	Viewpoint	View Direction	Description
June 12, 2008	Building 3A	West	Exposed Foundation Wall at the West End of the Concrete Trench

**Photodocumentation – Vibratory Finishing Area – Building 3A
Baldwin Hardware Manufacturing Corporation
Reading, Pennsylvania**



Date
June 12, 2008

Viewpoint
Building 3A

View Direction
North/Northwest

Description
West End of the Concrete Trench Showing the
Thickness of the Concrete Slab and Sub-Base Material

**Photodocumentation – Vibratory Finishing Area – Building 3A
Baldwin Hardware Manufacturing Corporation
Reading, Pennsylvania**



Date	Viewpoint	View Direction	Description
June 12, 2008	Building 3A	West	Subsurface Soil Beneath Concrete Trench/Slab and Sub-Base Material